

CARR - 766

522 HOOK ROAD

late 19th century

Westminster vicinity

private

522 Hook Road is a late nineteenth century farmhouse that demonstrates the rural Victorian farmhouse style found frequently in Carroll County. This style basically incorporates the regional characteristics with the addition of a gabled dormer. This example has a full-length, one-story front porch with brick piers that date from the twentieth century. There is a late nineteenth century bank barn on the property.



## DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street  
Westminster, Maryland 21157

## WESTMINSTER PLANNING DISTRICT

## FIELD SHEET--HISTORIC RESOURCES SURVEY

SURVEY NUMBER:	CARR-766
NEGATIVE FILE NUMBER:	
UTM REFERENCES:	Zone/Easting/Northing
U.S.G.S. QUAD. MAP:	Westminster
PRESENT FORMAL NAME:	
ORIGINAL FORMAL NAME:	
PRESENT USE:	residence
ORIGINAL USE:	residence
ARCHITECT/ENGINEER:	
BUILDER/CONTRACTOR:	
PHYSICAL CONDITION OF STRUCTURE:	
Excellent ( )	Good (X)
Fair ( )	Poor ( )
THEME:	
STYLE:	
DATE BUILT:	late 19th century

COUNTY: CARROLL  
TOWN: Westminster vicinity  
LOCATION: Barnes Ave.  
522 Hook Rd. TAX MAP 52 Block-3-P-458

COMMON NAME:

FUNCTIONAL TYPE:

OWNER: Ova Klougsted ?  
ADDRESS: 522 Hook Rd. Westminster

ACCESSIBILITY TO PUBLIC:

Yes ( ) No (X) Restricted ( )

LEVEL OF SIGNIFICANCE:

Local ( ) State ( ) National ( )

GENERAL DESCRIPTION:

Structural System

1. Foundation: Stone (X) Brick ( ) Concrete ( ) Concrete Block ( )
  2. Wall Structure
    - A. Wood: Log ( ) Post and Beam ( ) Balloon (X)
    - B. Wood Bearing Masonry: Brick ( ) Stone ( ) Concrete ( ) Concrete Block ( )
    - C. Iron ( ) D. Steel ( ) E. Other
  3. Wall Covering: Weatherboard ( ) German Siding ( ) Board and Batten ( )  
Wood Shingle ( ) Shiplap ( ) Novelty ( ) Stucco ( ) Sheet Metal ( )  
Aluminum ( ) Asphalt Shingle ( ) Brick Veneer ( ) Stone Veneer ( )  
Bonding Pattern: Other: Photos Siding
  4. Roof Structure
    - A. Truss: Wood (X) Iron ( ) Steel ( ) Concrete ( )
    - B. Other:
  5. Roof Covering: Slate ( ) Wood Shingle ( ) Asphalt Shingle ( ) Sheet Metal (X)  
Built Up ( ) Rolled ( ) Tile ( ) Other:
  6. Engineering Structure:
  7. Other:
- Appendages: Porches (X) Towers ( ) Cupolas ( ) Dormers (X) Chimneys ( ) Sheds ( )  
Ells (X) Wings ( ) Other:
- Roof Style: Gable (X) Hip ( ) Shed ( ) Flat ( ) Mansard ( ) Gambrel ( ) Jerkinhead ( )  
Saw Tooth ( ) With Monitor ( ) With Bellcast ( ) With Parapet ( )  
With False Front ( ) Other:
- Number of Stories: 2 1/2  
Number of Bays: 5 x 2  
Approximate Dimensions:
- Entrance Location: center

THREAT TO STRUCTURE:

No Threat ( ) Zoning ( ) Roads ( )  
Development ( ) Deterioration ( )  
Alteration ( ) Other:

LOCAL ATTITUDES:

Positive ( ) Negative ( )  
Mixed ( ) Other:

## ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

regional rural Victorian style

## RELATED STRUCTURES: (Describe)

late 19th c. bank loan

## STATEMENT OF SIGNIFICANCE:

representative of rural Victorian farmhouses in this region

## REFERENCES:

1862 Martenet's Map:

1877 LG &amp; S Atlas: William Beaver

## SURROUNDING ENVIRONMENT:

Open Lane ( ) Woodland ( ) Scattered Buildings ( )  
 Moderately Built Up (X) Densely-Built Up ( )  
 Residential ( ) Commercial ( )  
 Agricultural ( ) Industrial ( )  
 Roadside Strip Development ( )  
 Other:


## RECORDED BY:

Joe Kelly

## ORGANIZATION:

## DATE RECORDED:

8/83



U.S.G.S. MAP  
WESTMINSTER, MD.  
1:24000 SCALE

Mapped by the Corps of Engineers, U. S. Army  
Edited and published by the Geological Survey



CARR-766

Westminster vicinity

South facade

11/83

Photo By Joe Getty